00457R001900340007-1

Sanitized Copy Approved for Release 2

CENTRAL STATE OFFICIALS ONLY

50X1-HUM

. 2 .

- 5. During the first six months of 1948, the output of the factory increased by about 10% as a result of the arrival and installation of new machine tools and automatic machinery, such as non-centering grinding machines (beztsentrovochno shlifovalny stanok), thread knurling machines (rezbonakatny stanok), and automatic turning machines (tokarny avtomat).
- 6. In July 1948, Savin was the director of the factory; his deputy was Fomenko; and the chief engineer was Khelfits. the 50X1-HUM number of personnel of the factory at about 1,700 men.
- · 7. The main production shops of the factory are the following:

Drill shop (tackh sverl) Cutter shop (tackh frez) Tap shop (tsekh "schikov) Cutting die shop (tsekh plashek) Reamer shop (tsekh razvertok) Thermic (treatment) shop (termicheski tsekh) (well equipped with modern furnices for hardening tools) Grinding shop (zatodhny tsekh) Several auxiliary shops: Preparatory shop (zagotovitelny tsekh) Engineering shop (mekhanicheski tsekh) Laboratory with five sections: Chemical section (khimicheskoe otdelenie) Metallographic section (metallograficheskoe otdelenie) Cutting section (otdelenie rezaniya) Measuring section (izmeritelnoe otdelenie) Engineering section (mekhanicheskoe otdelenie)

8. High speed steel (bystrorezhanhchaya stal), carbon steel (uglerodistaya stal), and alloy steel (legir)vannaya stal) are received at the factory in form of rods and cylindrical lengths.

SECRET/CONTROL-US OFFICIALS ONLY